

Lesson Learned

Verification of Apparatus State within Switching Procedures

Primary Interest Groups

Distribution Providers (DPs)

Generator Operators (GOPs)

Generator Owners (GOs)

Transmission Operators (TOPs)

Transmission Owners (TOs)

Problem Statement

Operating personnel did not verify that all phases of a circuit breaker had opened following a switching operation in a generating station switchyard. The subsequent operation of an energized disconnect switch resulted in the inadvertent tripping of six 230 kV transmission lines and three generators.

Details

While preparing for an outage at a generating station, operating personnel performed switching operations. During switching, the "B" phase of a 230 kV breaker failed to open caused by a failure in its "B" phase operating mechanism. It was not readily apparent to plant personnel that the "B" phase on the breaker had failed in the closed position because the breaker physically indicated open via the 52a contact used in the protection interlocking scheme.

During subsequent switching, the opening of a 230 kV disconnect switch caused a phase-to-ground fault. The fault caused all six of the 230 kV lines feeding the station switchyard to trip at their remote ends and subsequently tripped three generators.

Corrective Actions

The entity modified its switching procedures to include verification that all phases of sources have actually been removed by breaker operation prior to operating disconnect switches.

Lesson Learned

When performing switching in a switchyard, it is advisable when operating switches (associated with power circuit breakers) to always confirm all three phases of the power circuit breakers are open using visual recognition or potential sensing devices to avoid making or breaking a connection with the associated disconnect switches. In addition:

- Entities should ensure plant personnel are trained and qualified to perform transmission switching.
 - Switching procedures should include three-part communications.
 - Operating personnel should reconfirm each step of the switching procedure.



When opening motor-operated disconnect switches and three-phase, gang-operated disconnect switches, always visually verify that all three phases of the switches have opened.

NERC's goal in publishing lessons learned is to provide industry with technical and understandable information that assists them with maintaining the reliability of the bulk power system. NERC requests that you provide input on this lesson learned by taking the short survey provided in the link below.

Click here for: Lesson Learned Comment Form

For more information, please contact:

NERC - Lessons Learned (via email)

Lesson Learned #: 20100702

Date Published: July 30, 2010

Category: Bulk Power System Operations

This document is designed to convey lessons learned from NERC's various activities. It is not intended to establish new requirements under NERC's Reliability Standards or to modify the requirements in any existing Reliability Standards. Compliance will continue to be determined based on language in the NERC Reliability Standards as they may be amended from time to time. Implementation of this lesson learned is not a substitute for compliance with requirements in NERC's Reliability Standards.