


Industry Webinar

Project 2015-10 Single Points of Failure

March 22, 2018











- Presenters
 - Standard Drafting Team
 - o Chair, Jonathan Hayes, SPP
 - Vice Chair, Delyn Kilpack, LGE-KU
 - Member, Chris Colson, WAPA
 - NERC Staff
 - Latrice Harkness
- Administrative Items
- Project 2015-10 Status
- FERC Order No. 754 and Order No. 786
- Implementation Plan
- Next Steps
- Questions and Answers



 It is NERC's policy and practice to obey the antitrust laws and to avoid all conduct that unreasonably restrains competition. This policy requires the avoidance of any conduct that violates, or that might appear to violate, the antitrust laws. Among other things, the antitrust laws forbid any agreement between or among competitors regarding prices, availability of service, product design, terms of sale, division of markets, allocation of customers or any other activity that unreasonably restrains competition. It is the responsibility of every NERC participant and employee who may in any way affect NERC's compliance with the antitrust laws to carry out this commitment.

NERC NORTH AMERICAN ELECTRIC RELIABILITY CORPORATION

NERC Public Disclaimer

Public Announcement

Participants are reminded that this meeting is public. Notice of the meeting was widely distributed. Participants should keep in mind that the audience may include members of the press and representatives of various governmental authorities, in addition to the expected participation by industry stakeholders.

Presentation Material

 Information used herein is used for presentation purposes and may not reflect the actual work of the official posted materials.

For the official record

- This presentation is not a part of the official project record.
- Comments must be submitted during the formal posting.



Standard Drafting Team (SDT)

Name	Organization/ Company
Jonathan Hayes (Chair)	Southwest Power Pool
Delyn Kilpack (Vice Chair)	Louisville Gas & Electric and Kentucky Utilities
Chris Colson	Western Area Power Administration
Bill Harm	PJM
Baj Agrawal	Arizona Public Service Company
Liqin Jiang	Duke Energy
Rich Kowalski	ISO New England
Prabhu Gnanam	ERCOT
Manuela Dobrescu Dobritoiu	Hydro-Quebec
Ruth Kloecker	ITC Holdings
Latrice Harkness	North American Reliability Corporation
Lauren Perotti, Counsel	North American Reliability Corporation



Status of Project 2015-10

- Project 2015-10 TPL-001-5 Single Points of Failure (SPF)
- This is the third posting
 - One informal posting
 - One formal posting
- TPL-001-5 addresses:
 - FERC Order 754 (SPF)
 - FERC Order 786 (Maintenance Outages in the Near Term Transmission Planning Horizon; stability analysis for loss of long lead time equipment)
- Separate ballot for standard and implementation plan



Changes to TPL-001-5:

- "Revision to Table 1 Steady State and Stability Performance Planning Events"
- Modified Category P5 event to include SPF
- Added a new Category P8 planning event
- Footnote 13 describes the non-redundant Protection System components considered for Category P5 and new Category P8 events
- Table 1:
 - Performance requirements for new Category P8
 - System shall remain stable, no cascading or uncontrolled islanding, for a 3-phase fault and failure of a non-redundant component of a Protection System.
 - When analysis indicates an inability to meet Performance Criteria, assessment must include Corrective Action Plan (CAP).



Reasons for New P8 Planning Event

- New P8 planning event defined for SPF to include a 3-phase fault and failure of a non-redundant component of a Protection System.
- Maintains the "Bright Line" distinction between Planning and Extreme events.
- SPF P8 Planning Event:
 - 3-phase fault are low probability single phase not properly cleared often evolves to a 3-phase fault.
 - The specific locations of SPF are known.
 - SPF role in system disturbances Section 1600 data request results System Protection Control Subcommittee (SPCS)/System Analysis and Modeling Subcommittee (SAMS) recommendation
 - Lower probability event is reflected in the P8 performance requirement.



FERC Order 786 (Maintenance Outage)

- Changes to Requirement R1 is not a prescriptive, continent-wide procedure
- Entity must have a process and procedure that conform with a technical rationale which must be made available
 - Consistent with other requirements in TPL-001-4, such as Voltage Criteria,
 Low Voltage Ride Through, etc.
- Removed the six-month time horizon for significant outages occurring within the period of the Near-Term Assessment studies (Year 1 or 2 and Year 5)



FERC Order 786 (Maintenance Outage)

- Categories P3 and P6 do not sufficiently cover planned maintenance outages
- Proposed revisions to Requirement R2 also include stability studies for long lead equipment that does not have a spare equipment strategy





- The issue is "raising the bar" on a continent-wide basis
 - Closer coordination between Protection and Planning
 - Worst case: some entities may require coordination efforts that involve multiple substation outages to affect SPF corrective actions.
- "Raising the bar" issue was addressed in TPL-001-4 by:
 - Five-year time period for those requirements that "raised the bar"
 - Providing temporary relief from the performance requirements by permitting Operating Procedures during the phase in period to include Non-Consequential load loss and curtailment of Firm Transmission Service that would not otherwise be permitted by the requirements of TPL-001-4

Implementation



- The implementation plan is being balloted separately and contains:
 - 3 year study period to perform the "raising the bar" events in P5 and P8
 - 2 year period to identify CAPs
- The relief provided in TPL-001-4 is not portable to TPL-001-5
 - In TPL-001-4, a P5 (non-redundant relay failure) event which does not meet performance requirements must have Operating Procedure until the redundant relay is installed.
 - Options provided in bullets under Requirement 2 Part 2.7.1 may cause a BES reliability issue that is more severe than a low probability P5 event.
 - There is not time to install the added redundancy of the protection system for P5 or the added P8.





- The failure to meet system performance requirements presented during dynamic simulations of Categories P5 and P8 events is more difficult to mitigate.
- The solution to a relay issue is often to add a redundant relay.
 - "For CAPs developed to address failures to meet Table 1 performance requirements for P5 or P8 events only, Transmission Planners and Planning Coordinators shall not be required to comply with the section of Requirement R2, Part 2.7 that states: 'Revisions to the Corrective Action Plan(s) are allowed in subsequent Planning Assessments but the planned System shall continue to meet the performance requirements in Table 1', until 96 months after the effective date of Reliability Standard TPL-001-5."



Comment period

- Project 2015-10 page
- 45-Days February 23– April 23, 2018
- Ballot April 13 April 23, 2018
- Respond to Comments
 - May 2018
- Point of contact
 - Latrice Harkness, Senior Standards Developer
 - <u>Latrice.Harkness@nerc.net</u> or call 404-446-9689
- Webinar posting
 - 48-72 hours
 - Standards Bulletin





Informal discussion

- Via the Q&A feature
- Chat only goes to the host, not panelists
- Respond to stakeholder questions

Other

- Some questions may require future team consideration
- Please reference slide number, standard section, etc., if applicable
- Team will address as many questions as possible
- Webinar and chat comments are not a part of the official project record





Questions and Answers







Webinar has ended - Thank you